

NRC Publications Archive Archives des publications du CNRC

Failed and failing rivets: the correlation to corrosion

Gould, Ronald; Overton, J.; Harrison, M.; Bellinger, N.; Chapman, C. E.;
Brothers, M.; Forsyth, D.

For the publisher's version, please access the DOI link below./ Pour consulter la version de l'éditeur, utilisez le lien DOI ci-dessous.

<https://doi.org/10.4224/40002724>

NRC Publications Archive Record / Notice des Archives des publications du CNRC :

<https://nrc-publications.canada.ca/eng/view/object/?id=c6ebf0d5-dc0d-495f-b4d1-84cf7e78f264>

<https://publications-cnrc.canada.ca/fra/voir/objet/?id=c6ebf0d5-dc0d-495f-b4d1-84cf7e78f264>

Access and use of this website and the material on it are subject to the Terms and Conditions set forth at

<https://nrc-publications.canada.ca/eng/copyright>

READ THESE TERMS AND CONDITIONS CAREFULLY BEFORE USING THIS WEBSITE.

L'accès à ce site Web et l'utilisation de son contenu sont assujettis aux conditions présentées dans le site

<https://publications-cnrc.canada.ca/fra/droits>

LISEZ CES CONDITIONS ATTENTIVEMENT AVANT D'UTILISER CE SITE WEB.

Questions? Contact the NRC Publications Archive team at

PublicationsArchive-ArchivesPublications@nrc-cnrc.gc.ca. If you wish to email the authors directly, please see the first page of the publication for their contact information.

Vous avez des questions? Nous pouvons vous aider. Pour communiquer directement avec un auteur, consultez la première page de la revue dans laquelle son article a été publié afin de trouver ses coordonnées. Si vous n'arrivez pas à les repérer, communiquez avec nous à PublicationsArchive-ArchivesPublications@nrc-cnrc.gc.ca.

FAILED AND FAILING RIVETS the Correlation to Corrosion

•Large population failed and fractured

The disassembly of a number of corroded fuselage joints has revealed instances where a large population of the rivets had failed (heads popped off) or fractured. This raised concerns about the integrity of the structure. The widespread nature of this deterioration needs to be considered in any analysis of residual strength.

•Replacement rivets fractured too

It is known that the rivets are highly stressed and so susceptible to environmentally assisted cracking under sustained stress (EAC_{ss}) especially at the base of the countersink.

•Most fractures at base of countersink

Where many fractures were initially masked by corrosion products, others were hidden by the faying surface adhesive. In both cases the obscuring substance had to be chemically dissolved to locate and determine the extent of the fracture.

The skins affected were found to be suffering from varying levels of corrosion damage but most were at low levels of thickness loss.

•No evidence of multi-site fatigue damage

•Pillowing cracks have been found

Ultrasonic NDI techniques have detected failed rivets but this technique is not normally used to inspect fuselage lap joints.

Conclusions


- Individual or combined skin thickness loss, as a result of corrosion, does not correlate to the fracturing of associated rivets. Neither does the pillowing of the skins.

- Modeling of joints should consider rivet failure or degradation of rivet function in the joint at low corrosion levels.

- Rivet failures and fractures are caused by inherent high tensile stress condition and the presence of a corrosive environment.



- The demonstrated susceptibility of rivets to EAC_{ss} requires further study particularly the determination of the residual strength of effected joints.

- At present, following the detection of one failed rivet the maintainers are advised to replace an array of the adjacent rivets.




ASL#253, 34M before & after cleaning

48 Rivets
4 Failed
32 Fractured
0 Replaced
12 OK
75% of fasteners are distressed







108 Rivets
13 Failed
31 Fractured
18 Replaced *
46 OK
57% of fasteners are distressed



* The 17 replacement rivets at the LH end were installed into severely exfoliated second layer skin and stringer




93 Rivets
0 Failed
43 Fractured
1 Replaced *
49 OK
47% of fasteners are distressed



Before Cleaning
After cleaning ASL#253 32M

* Replacement rivet at M24 is also fractured ↑

85 Rivets
2 Failed
32 Fractured
5 Replaced *
49 OK
43% of fasteners are distressed



ASL#20 T2,T3,T4