ARCHIVE

## NATIONAL BUILDING CODE OF CANADA 1985

## **SEVENTH REVISIONS**

Issued by the

Associate Committee on the National Building Code National Research Council of Canada Ottawa

January 1989

## Revisions to the National Building Code of Canada 1985

The following revisions to the National Building Code of Canada 1985 have been approved by the Associate Committee on the National Building Code for immediate implementation.

In accordance with the ACNBC Policies and Procedures, the list of referenced documents in Table 2.7.3.A. of the 1985 NBC are updated annually. The First, Fourth and Fifth Revisions, dated January 1986, January 1987 and January 1988, respectively, included updating of the referenced documents to 30 June 1987. The revisions contained herein include additional updates to 30 June 1988.

1

| Page | Reference      | Revision   | 2 |
|------|----------------|--|---|
| 21   | 2.7.3.1.       | Change the last line to read "30 June 1988"                    |   |
| 4    | Table 2.7.3.A. | Revise entries in Columns 2 and 3 where applicable as follows: |   |

| Column 1          | Ca                           | olumn 2                          | Column 3   |
|-------------------|------------------------------|----------------------------------|--|
| Issuing<br>Agency | Document                     | Title or Document as revised (1) |  |
|                   | Existing Number              | Revised Number (1)               |  |
| ASTM              | A283/A283M-85 <sup>(2)</sup> | A283/A283M-87                    |  |
| ASTM              | A570/A570M-85 <sup>(2)</sup> | A570/A570M-88                    |  |
| ASTM              | C315-78c(1983)               | C315-87                          |  |
| ASTM              | C700-86 <sup>(3)</sup>       | C700-88                          |  |
| ASTM              | E90-85 <sup>(2)</sup>        | E-90-87                          |  |
| CGSB              | 11-GP-5Ma-1978               | CAN/CGSB-11-5M-87                | Hardboard,<br>Precoated, Factory<br>Finished, for Exterior<br>Cladding |
| CGSB              | 34-GP-1M-1976                | CAN/CGSB-34.1-M87                |  |
| CSA               | CAN3-G40.21M81               | CAN/CSA-G40.21-M87               |  |
| CSA               | 0118.1 <b>M</b> 1980         | CAN/CSA-0118.1M88                | Western Red Cedar<br>Shingles and<br>Shakes                            |
| NFPA              | 71-1985 <sup>(2)</sup>       | 71-1987                          |  |
| NFPA              | 96-1984                      | 96-1987                          |  |
| NFPA              | 214-1983                     | 214-1988                         |  |
| NLGA              | 1984 <sup>(2)</sup>          | 1987                             |  |
| ULC               | \$107-M1980                  | CAN/ULC-S107-M87                 | Standard Methods<br>of Fire Tests of<br>Roof coverings                 |
| ULC               | S109-M1980                   | CAN/ULC-S109-M87                 |  |

Revised document numbers and titles also apply in the appropriate code references listed in Column 4.
Previously updated in Fourth Revisions dated January 1987.
Previously updated in Fifth Revisions dated January 1988.